

职业卫生检测报告公示

用人单位名称	浙江磐安造漆厂
地址	浙江省磐安县仁川镇
联系人	陈总
项目组成员	蔡晓雯、何剑东、胡国涛
现场调查人员	蔡晓雯
现场调查时间	2021. 11. 29
现场采样/检测人员	何剑东、胡国涛
现场采样/检测时间	2021. 11. 30
用人单位陪同人	陈总
现场图像	 The '现场图像' (On-site Images) section contains four photographs. The top-left photo shows the exterior of the '浙江磐安造漆厂' (Zhejiang Pan'an Paint Factory) with a stone sign in the foreground. The top-right photo shows a worker in a blue jacket operating a large industrial machine with a circular table and a hood. The bottom-left photo shows a different part of the factory interior with various pipes and machinery. The bottom-right photo is a close-up of a hand holding a 3M 3001CN respirator mask, with its packaging visible in the background.