

### 职业卫生检测报告公示

用人单位名称	磐安县宇龙电器配件厂
地址	浙江省金华市磐安县新渥街道孵化园创业路 88 号
联系人	孙海洋
项目组成员	张新宇、张虹、郑国荣
现场调查人员	张新宇、张虹
现场调查时间	2022.10.27
现场采样/检测人员	郑国荣、张新宇
现场采样/检测时间	2022.10.28
用人单位陪同人员	孙海洋
现场图像	 <p>The collage consists of six photographs arranged in a 2x3 grid. The top-left photo shows two men standing in front of a factory gate with a sign that reads '宇龙电器'. The top-right photo shows a worker in a purple jacket operating a large industrial machine. The middle-left photo shows a worker in a blue jacket being interviewed by a person holding a microphone. The middle-right photo shows a worker in a blue jacket operating a machine with a large dust collector. The bottom-left photo shows a worker in a black shirt being interviewed by a person holding a microphone. The bottom-right photo shows a worker in a blue jacket operating a machine with a large dust collector in a different area of the factory.</p>